


Charge Gas Compressor Fourth Stage Vibration

Johnny Dugas
Senior Technical Associate
DuPont Sabine River Works
Orange, Texas


Problem

- Radial Vibration Spiked to 4 mils Upon Start-up from 2/3 Stage Outage
- Internal Fouling was the Suspected Cause

GB201 Compressor Train





4th Stage Vibration Trend



4th Stage Orbit

New Plot Session7 - OrbitTimebase Plot [New Plot Group] Plot 1

Y: 201 Stg4 ER 328-1 S $\angle 45^\circ$ Left SYNCH WF AMP : 3.12 mil pp
X: 201 Stg4 ER 328 N $\angle 45^\circ$ Right SYNCH WF AMP : 3.46 mil pp
GB201 Charge 30JUN2005 17:55:11 HW Alert/Alarm Direct 6929 rpm
FS: 0-64 X SMPR: 128/8



ROTATION: X TO Y (CCW)

Wash Oil Flush

- Attempted to Remove Suspected Fouling by High Volume Oil Flush
- 8000 Gallons Used
- No Effect on Vibration

Shutdown/Overhaul

- Opened Case and Found Indications of a Watermark on Rotor and Diaphragms
- Close Examination Showed Top Layer of Antifoulant Coating was Missing











As-Found Rotor Balance Check

Balance Procedure:						REQUIRED INFORMATION	
Full Assembly Bal.	<input type="checkbox"/>	Check Bal.	<input type="checkbox"/>	Individual Bal.	<input type="checkbox"/>	<input type="checkbox"/>	AS RECEIVED
Type of Rotor:						<input type="checkbox"/>	AFTER REPAIR
Turbine	<input type="checkbox"/>	Compressor	<input checked="" type="checkbox"/>	Other	38M6-5 Rotor	<input type="checkbox"/>	NEW
Wheel/Disk Number				Shaft only	<input type="checkbox"/>	<input type="checkbox"/>	FINAL
Balance Machine Used:	5000 lb. IRI			Balance Speed	700	RPM	
Balance Tolerance:	.27 TOTAL			oz-in/gr-in per	API	Specifications	
Rotor Weight:	1409 lbs			Operating Speed	7287	RPM	
Correction Radius:	6			Inch(es)	Coupling	End	
	6.5			Inch(es)	THRUST	End	
Initial Balance Machine Readings:							
49.167	oz./gr.	at	242	Degrees on	Coupling	End	10.405 oz-in/gr-in
91.481	oz./gr.	at	241	Degrees on	THRUST	End	20.974 oz-in/gr-in
Static Corrections:							
Initial	oz./gr. at			Degrees on			End oz-in/gr-in
Final	oz./gr. at			Degrees on			End oz-in/gr-in

As-Found Rotor Balance Check


Left Radius 6.000 inch	Distance a 15.750 inch	Distance b 42.500 inch	Distance c 61.250 inch	Right Radius 6.500 inch
Balancing speed 705 RPM		Left Tolerance 14.770 g-inch	Right Tolerance 15.791 g-inch	
INITIAL RESULT:				
Correction Weight: Unbalance:	Left - 49.167 g at 242° 295.005 g-inch Reject (19.97 x Tol)		Right - 91.481 g at 241° 594.629 g-inch Reject (37.66 x Tol)	
CURRENT RESULT:				
Correction Weight: Unbalance:	Left - 47.117 g at 242° 282.702 g-inch Reject (19.14 x Tol)		Right - 89.982 g at 240° 584.883 g-inch Reject (37.04 x Tol)	
<p>Scale: 100.0 g</p> 		<p>Scale: 100.0 g</p> 		

Balance Check of Rotor

- 585 Gram-inches Unbalance on Suction End of Rotor
- 283 Gram-inches Unbalance on Discharge End of Rotor
- Phase Angle Essentially Identical
- 2560 Pounds of Force at 7000 rpm (Rotor Weighs 1409 Pounds)

What Caused the Coating Loss?

- Misvalving Caustic Wash System Backed Caustic Water into Fourth Stage Compressor Case
- Case Drains Plugged



Summary

- High Vibration Due to Rotor Unbalance from Loss of Antifoulant Coating
- Coating Loss due to Caustic Water Filling Casing While Charge Gas Compressor Train Down for 2/3 Stage Overhaul
- Procedures and Check-sheet have been Revised to Prevent Recurrence

